

CORRIGENDUM

Reference:

- i) DNIEt No: 07/SE-II/PWD(R&B)/2024-25,
- ii) PNIEt No : 07/EE/Divn.III/PWD(R&B)/2024-25,
- iii) Memo No. F.45(04)/EE/Divn.III/PWD(R&B)/2196-2264, dated 25.07.2024

Please read the name of work against the DNIEt No. 07/SE-II/PWD(R&B)/2024-25, on the PNIEt No. 07/EE/Divn.III/PWD(R&B)/2024-25 as

Maintenance of road from GB Bazar to RCC bridge over Indranagar Katakhal via Indranagar Kalibari during the year 2024-25/SH: Patch soling, WBM-2, WBM-3, patch DBM, BC and other allied works (length = 2.16 KM),
in place of

Maintenance of road from Indranagar ITI to RCC bridge over Indranagar Katakhal via Indranagar Kalibari /SH: Cover Drain, Footpath, GSB, WBM-2, WBM-3, DBM, BC and other allied works (length = 2.16 KM).

ICA/C/1044/24


31/7/2024

(Er. M. Debnath)
Executive Engineer
Agartala Division No.III, PWD(R&B)
Agartala, West Tripura.